VISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Lot 611 PROPERTY RECORDED: _____
'ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	BSCL GR	FRI SSSP					PS -3
		6-24	RC SPK	FRI SSSP					
		24-48	CL WSPK	FRI SSSP	core of Sap				
2		0-4	BSCL GR	FRI SSSP					PS -3
		4-36	RC SPK	FRI SP					
		36-50	VFCL WSPK	FRI SSSP	R Limiting SC SAP Inc.				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)		
stem Type(s)		
te LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


134'
119'
186'
612
43 Sq.Ft.
378'
362'
611
49,378 Sq.Ft.
610
53,827 Sq.Ft
765
770
775
780
785
790
Excavate & Save Repair
10'x70' SIGHT TRI.
136'
145'
631
39,990
DRIVE
TANDISH AVENUE
50' PUBLIC R/W
12+00
11+00
27+00
25+00
26+00