ENVIRONMENTAL HEALTH
WASTEWATER SECTION

PROPERTY I.D.:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICANT:
APPLICATION DATE: DATE EVALUATED: 3-26-04
ADDRESS:
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: Lot 1309 SFE lot 13th Pl. PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	1353 TCU 1302A	0-24	gr-wk sbk RL/SL	frss sp					.3
		24-48	wk sbk RscL	frss sp sap					
2	1302A	0-5	wk sbk R brn SL	frss p					.4
		5-18	(B-C) wk sbk Ry SL/L	frss p sap	common mil sap				
		18-51	massive gy SL sap	frss p					
3		0-7	wk sbk R brn SCL	frss p					.3
		7-42	m sbk rc/cl	fr ss p sap					
		42-52	massive LS sap	frss p					
4	59 TCU	0-7	gr brn SL	fr ss p					.3
		7-32	wk sbk RC	frss p					
		32-48	wk sbk LRCL	fr ss p	common mil sap				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: