TE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: CRL APPLICATION DATE _____

DDRESS: _____

ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 480 gpd DATE EVALUATED: March 5, 04

OCATION OF SITE: ph 13 The Point lot 1349 PROPERTY SIZE: _____

ATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____

VALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

YPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12	gr-wkfsbk vfrsdscl	frsssp	few-common gbrw mottles				.25
		12-36	mkfsbk RC	fr ss sp sepp					
		36-52	wkfsbk RCL	frsssp	few-common brw mottles				
2		0-6	wkfsbk vfrsdscl	frsssp	few-common ybrw mottles				.25-.3
		6-25	mkfsbk RC	fr ss sp sepp					
		25-49	wkfsbk yrcl	frsssp					
3	#36 TCJ	0-8	wkmsbk cl	frsssp	few med distinct ybrw mottles				.3
		8-28	BT mkfsbk RC	fr ss sp sepp					
		28-50	B-C mkfsbk yrcl	frsssp					
4		0-8	gr-wkfsbk vfrsdscl	frsssp					.15
		8-27	mkfsbk RC	fr ss sp sepp	some water seeping in from ditch channel				
		27-48	wkfsbk yrcl	fr ss sp common - many ybrw mottles					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

OMMENTS: _____