

559
31,542. sq.ft.
70x80
560
41,135. sq.ft.
CRAWL
90x100
BASEMENT
561
40,350. sq.ft.
CRAWL
70x80
BASEMENT
562
33,582. sq.ft.
CRAWL
70x80
BASEMENT
563
32,036.
DRIVE
DRIVE
DRIVE
DRIVE
35' SETBACK
84.9' SETBACK
93.7' SETBACK
330'
254'
124'
124'
107'
37'
37'
37'
795
800
785
780
775
770
765
93'
116'
N81°14'04"W
322.21'
208.
154'
259.

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-28-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 561 phase 5 The Pit PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-16	gr. sandy loam						PS .3
		16-55	mbk BC	f friable slightly sticky slightly plastic					
2	#35 TCS	0-7	sandy C						PS .3
		7-48	mbk yco	common med stg					
		48-58	yc-LSp						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____