IREDELL COUNTY HEALTH DEPARTMENT

12023

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C) 4625 80 6817

OWNER OR CONTRACTOR Richard ~~Hilton~~ Fowler AWS DATE 2/5/91 PERMIT NO. 2C-2-A-28

PHONE: Business _____ Home 548-0665

LOCATION YACHT COVE, 1st House on ⓡ after bend in road - Brawley School Rd, TL 1182, bear ⓡ first house on ⓛ S. R. No. ~~1182~~ OFF 1182

SUBDIVISION NAME YACHT COVE LOT NO. 28 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2 1/2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil clay
Percolation Rate .4
Topography 1-3%
Depth to Water Table > 48"
Rock or other impervious formations None found

Lot Area 20,000 Ft²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement 1000 SLT



Plot of System

Size of Tank 1500 P/T Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 1080 Linear Ft. 360
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Benchmark Grading

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: 2" PVC in 3' wide ditches, 5/32" hole every 5' in length. Pressure head set for 2' on end of each lateral. 7" stroke on pump

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 2/5/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold