N OF ENVIRONMENTAL HEALTH
WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: LOT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-18-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: LOT 511 phase 5 The Pl PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8							
		8-32							
		32-53							
2		0-10							
		10-40							
		40-50							
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


Pervious Area
Top of Level Lot with Retaining Wall
133'
765
207'
770
BASEMENT
70x90
33,922. sq.ft.
512
CRAWL
246'
BASEMENT
29,243 sq.ft.
70x85
511
CRAWL
780
238'
BASEMENT
70x90
39,574. sq
CRAWL
510
SETBACK
35'
DRIVE
POLPIS RC
80'
9,585. sq.ft.
513
790
160'
57'
60
122'
R=42'
N83°09'47"E
96.50'
795
24+94.48
24+00
40'
R/W
24'
BOC
23+00
R=50'
23+97.8
PT
785
84.9' SETBACK
175'
DRIVE
53'
780
515
CENTERLIN
R=150.00
L=366.30
Tan=411.1
Delta=139