VISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-18-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 507 phase 5 The Pt. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-16	SAB prc	fr sp					PS .3
		16-56	wk SAB prcl	common med SAB	fr ss sp	SLOP			
2		0-30	mmk SB RC	fr sp					PS .3
		30-48	mfsab yrcl	few med SAB	fr ss sp				
			gets better w/ depth — maybe 36"-48"						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


WELL SITE #6
515
CENTERLINE
R=150.00
L=366.30
Tan=411.19
Delta=139°54'59"
N43°04'46"E
329.81'
R/W
40'
BOC
22'
481'
805
143'
147'
800
793'
790
83'
SETBACK
DRIVE
506
CRAWL
70x70
BASEMENT
507
CRAWL
70x100
BASEMENT
508
254'
271'
129'
150'
785
S68°39'58"E
240.63'
S25°40'19"W
278.55'
S11°44'20"E
167.37'