DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: CBT APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 2-17-99
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 269 Phase 2 The Vi PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

#5-Near 0-12 SAB
12-30 RCL many
30-48 RCL many

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6							PS .3
		6-28							
		28-48							
2	#37 TCS	0-6							PS .2-.25
		6-52							
3	#29 TCS								PS .25
4	#38 TCS	0-4							PS .3
		4-24							
		24-50							

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___


S 53°48'20" E
65.52'
109.04'
L6
U1.59'
S 01°24'49" E
225.12'
35' MBS
149.40'
203.00'
S 33°30'32" W
155.37'
267
41,524 SF
0.953 AC
S 40°42'03" E
195.17'
C5
53.60'
R/W
S 88°35'11" W
C2
EP
EP
C1
L1
35' MBS
265A
RESERVED FOR SEPTIC
C4
50'
269
50,579 SF
1.161 AC
110.00'
240.00'
S 40°42'03" E
165.01'
C6
C3
268
40,565 SF
0.931 AC
S 49°17'57" W
102.46'
BRAWLEY HARBOR PLACE
50' PUBLIC R/W
S 49°17'57" W
102.46'
10'X70' SIGHT TRIANGLE (TYP)
270A
RESERVED FOR SEPTIC
130.00'
35' MBS
11.02'
140.00'
C3
100.00'
N 40°42'03" W
464.95'
C7
N 40°42'03" W
464.95'
BRAWLEY SCHOOL ROAD, S.R. 1100 (90' PUBLIC R/W)
PROPOSED 90' R/W

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 2-2-99
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Phase II The Pt. lot 268 (265A - 304) — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1		0-5	brn sL						PS .3
		5-29	sbk						
		29-54	mSBK						
2		0-5	brn sL						PS .25
		5-29							
		29-51							
			36"						
3		0-7	sL						PS .3
		7-29							
		29-47							
		47-55							
4		0-5	sL						PS .3
		5-30							
		30-60							

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

#5 0-6 comp sL 6-25 [illegible]