SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: CRE APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-21-92
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 64 The Pointe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

Now Lot 63

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-25	sgrb R CL	fr sss so sp					PS -3
		25-43	wk sab gr L sm	fr ss sp sy					
2	PS #101	0-16	wk sab gr vfsl	fr ss sp					PS -3
		16-28	wk sab gr vfsl	fr ss sp					
		28-50	M sab gr vfsl	fr ss sp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


42,352. sq.ft.
65
34,562. sq.ft.
64
41,334. sq.ft.
63
37,595. sq.f
61
359'
283'
266'
128'
126'
120'
140'
184'
184'
212'
212'
150'
129'
L325
S71°28'45"E
86.85'
20' PSDE
224'
257'
R=300.00'
L=206.60'
Tan=107.58'
Delta=39°27'26"
95.00'
8.58'
85.11'
=19°30'46"
DRIVE
CRAWL
Bas
ent