4626008268

09687

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Phillip S. Aull DATE March 12, '90 PERMIT NO. 2E-1-A-147

PHONE: Business _____ Home _____

LOCATION 1100 TR 1177 (Chuckwood) TR Barber Loop ~3/4 mile on left S. R. No. _____

SUBDIVISION NAME CLOT / LAKE NORMAN LOT NO. 147 SECTION OR BLOCK NO. 7


House (✓) Mobile Home ( ) Business ( ) Other Adding GARAGE / downgrading from 3 small bedroom TO 2 bedrooms W/Addn.

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil		
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate		
Auto. Wash. Machine	Yes (✓)	No ( )	Topography		
Site Suitable	Yes ( )	No ( )	Depth to Water Table		
			Rock or other impervious formations		

Lot Area ±.64AC

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank Existing Gals.

Nitrification Field:

No. of Lines Existing

Sq. Ft. _____ Linear Ft. 0

Depth of Stone in Lines _____

Water Supply: Individual ( )
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing system showing no sign of malfunction at time of inspection.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: [signature], EHS DATE 3-12-90

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold