DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Steve Sebang
ADDRESS: 134 Lakeheaven Ln. (L)
APPLICATION DATE _____
PROPOSED FACILITY: Home PROPOSED DESIGN FLOW (.1949): 480 max. DATE EVALUATED: 7/15/04
LOCATION OF SITE: CL+T Sec 7 Lot 78 PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	GR / l	VFR - NSNP	7R				
		9-20	wk sbk / cl	FI SS - SP	PS / R				
		21-30	sbk / cl	FR - SS - SP	/ 4R				
		31-37	F sbk / l SAP	VFR - SS - NP	/ 7R				
		38-51	GR / l SAP	VFR - SS - SP	PS / 7R				
2		0-5	GR / l	FR - SS - NP	/ B				
		6-22	sbk / cl	FR - SS - SP	/ R				
		23-40	FR sbk / cl / 7R	FI - SS - SP	/ 7R				
		41-49	SM sbk / cl / 7R	FR. SS-SP.	/ Rock R.				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ABAND. DELL, SIZE HOUSE
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: Steve Sebang Jr.

COMMENTS: _____