)IVISION OF ENVIRONMENTAL HEALTH
)N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

)WNER: Mike Levine APPLICANT: _____
.DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8/11/00
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: _____ PROPERTY RECORDED: _____
/ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | Pit 1 | 0-7 | Rd/Brw SCL GR FR | | | | | | PS .3 |
| | | 7-27 | Rd/Brw C/CL mSBK SS, SP, SE, FI-FR | | | | | | |
| | | 27-56 | Rd/Brw CL wSBK SS, SP, SE FR w/ Some SAP Inclus & Common Mica | | | | | | |
| 2 | Pit 2 | 0-14" | ~~Rd/Brw~~ Compacted (3-4" gravel) | | | | | | PS .3 |
| | | 14"-34" | Rd/Brw C/CL m-wSBK SS, SP SE FI FR | | | | | | |
| | | 34-56" | Rd/Brw CL wSBK SS, SP SE FR w/ Some SAP/ Inclus. & Common Mica flakes | | | | | | |
| 3 | Pit 3 | 0-10" | Brw SCL GR FR | | | | | | PS .25 |
| | | 10-35" | Rd/Brw C/CL m SBK SS, SP, SE, FI-FR | | | | | | |
| | | 35-54" | Rd/Brw CL wSBK SS, SP, SE, FI-FR | | | | | | |
| | | | View of Rd/Brw Weathered Rock Cutting through | | | | | | |
| | | 0-12" | Compacted - Old Driveway or Rd Bed | | | | | | PS .25 |
| | | 12-36 | Rd/Brw C/CL m-wSBK SS, SP, FI-FR | | | | | | |
| | | 36-54" | CL w/ View of Quartz Rock on one side CL on other Side wSBK SS, SP, SE, FI-FR | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| vailable Space (.1945) | | |
| 'stem Type(s) | | |
| te LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Mike Levine APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8/10/22
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-24" | Rd/Brn C/Cl m SBK | | S-SS, SP, SE | | FR | | Upl 24" |
| | | 25" | Hard w. Rock/SAP | | | | | | |
| 2 | | 0-24" | Rd/Brn C/Cl m SBK | | S-SS, SP, SE, | | F-FR | | Upl 24" |
| | | 25" | Hard w Rock/SAP | | | | | | |
| 3 | | 0-6" | Rd/Brn SCl | | SS, SP, SE, | | F-FR | | PS .3 |
| | | 6-48" | Rd/Brn C/Cl m-w SBK | | | | | | |
| | | | few SAP Tubes | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____