DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Michael Schutrum
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 360 gpd DATE EVALUATED: 11-14-06
LOCATION OF SITE: _____ PROPERTY SIZE: 11a-06
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	6/20 linear	0-4	lsbkcl						
		4-48	lsbk C	Cr ss/sp SE		48			.3
2		0-3	lsbk cl						
		3-48	lsbk C	Cr		48			.3
			+ few stones/sap						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)	Yes	yes
stem Type(s)	LPP and	same
e LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TMelville
OTHER(S) PRESENT: _____
IMENTS: _____

Division of Environmental Health
On-site Wastewater Section

Property ID: 4626-07-8014
Lot #: CL&T-8-174
File #:
AppID:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: MICHAEL SHUTRUM
Applicant: SAME
Address: 16039 AGINCOURT DR HUNTERSVILLE 28078
Date Evaluated: 10/1/2009
Proposed Facility: SFR Design Flow (.1949) 480
Property Size: .689 AC
Location of Site: BSR, TR MCKENDREE, TL 2ND KEMP, ON LEFT
Property Recorded: YES
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY 1941 1941 Structure/ Texture	1941 Consistence Mineralogy	b PROFILE FACTORS 1942 Soil Wetness/ Color	1943 Soil Depth (IN.)	1956 Sapro Class	1944 Restr Horiz	Profile Class & LTAR
1	6%	0-24	C,M,SBK	SS,SP,SEXP,FR	NA				
	LINEAR	24-48	CL,M,SBK	SS,NP,NEXP,VFR	MANY MICA	48"	NA	NA	.35
2	6%	0-34	C,M,SBK	SS,SP,SEXP,FR	NA				
	LINEAR	34-48	CL,M,SBK	SS,NP,NEXP,VFR	MANY MICA	48"	NA	NA	.35

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	LP-PANEL	LP-PANEL
Site LTAR	.35	.35

Other Factors (.1946):
Soil Evaluation By: BEN ALDRIDGE
Others Present: MIKE ATHANAS
Site Classification (.1948): PS
Site Evaluation By: BEN ALDRIDGE
Others Present: MIKE ATHANAS

Sheet:
FILE #:

COMMENTS: SITE ORIGINALLY PERMITED FOR 3 BEDROOMS. Now evaluating for 4 bedrooms.