DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Applicant: Tonda Wynn
ADDRESS: _____
PROPOSED FACILITY: _____
LOCATION OF SITE: 114 Pentland Ct.
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut

APPLICATION DATE _____
DATE EVALUATED: 1-27-06
PROPOSED DESIGN FLOW (.1949): 120 gpd expansion
PROPERTY SIZE: .6 Ac
PROPERTY RECORDED: _____
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1			0-24	1sbkc		48			PS .3
			24-48	1sbkc+sap					
			approaching						
				50% sap at 40"					
2			0-30	1sbkc		48			PS .3
			30-48	1sbkc+sap					
3	front yard repair		0-30	1sbkcl		48			PS .3
			30-48	1sbkcl+sap					
			48	sl sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	25%	Conv
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: J. Melville
OTHER(S) PRESENT: _____

COMMENTS: _____