SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICATION DATE _____

SS: _____ DATE EVALUATED: _____

SED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

ION OF SITE: 359 Farm site PROPERTY RECORDED: _____

. SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

F WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-13	BSCL FSSK	fri SSSP					PS .275
	13-37	RBC MSBK	fi S P	+ mang.				
	37-53	RBCL Medium	fri SSSP	+ mang. concretions				
	0-11	BSCL VFR	fri SSSP slap					PS .25 - 3
	11-52	RCL SBK	fri SSSP slap					
	0-48	Sat Hydrolic BR	MMABK/SBK fri	Mang.				PS .25

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
.ble Space (.1945)		
n Type(s)		
..t		


OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

ENTS: _____


351
0.94 Ac.
Linde
45' Blv
PC = 60+83.33
PT = 60+66.76
61+00
60+00
59+00
58+00
1+00
66'
42'
DRIVE
DRIVE
DRIVE
105'
76'
30'
23'
SETBACK
84'
60.61'
60'
70x18
70x80
360
1.00 Ac.
358
0.83 Ac.
359
1.10 Ac.
297'
221'
Gravity
25%
+
LP Panel
75'
87'
98'
76'
8"RCP
INV=767.38
8"PVC
INV=777.05
8"PVC
INV=777.01
MB
MB
MB