S7 LOT 31

4626-23-9097

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Louis Lipinsky DATE 10/17/88 PERMIT NO. _____

PHONE: Business _____ Home 664-5719

LOCATION 1100 TR 1177 (Chuckwood) TR 1238 (Indian Trail) ~.8 mile on left. S. R. No. _____

SUBDIVISION NAME C L and T LOT NO. 31 B SECTION OR BLOCK NO. _____
subdivided from original lot 31.

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ P.S. Yes (✓) No ( )

Character & Porosity of Soil Silty clay
Percolation Rate ~.3 gpd/ft2
Topography 15-25%
Depth to Water Table 4'+
Rock or other impervious formations Scattered rock 3'+ massive rock near lake

Lot Area 1.08 Acre

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NOT TO SCALE

1250 gal pump tank

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. _____ Linear Ft 200' of
Depth of Stone in Lines 16" T and I Panels
Water Supply: Individual (✓) Pressure Dosed
Public ( )

Installed by F.J. Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY ACP

COMMENTS: Alarm and floats installed but high water alarm not mounted. Should be mounted.

CERTIFICATE OF COMPLETION BY Andre C. Pina DATE 10/17/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold