SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

: _____ APPLICATION DATE _____

SS: _____ DATE EVALUATED: _____

SED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

ION OF SITE: 363 Farm III PROPERTY RECORDED: _____

. SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

F WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-52	RC SM/SM	fri ssSP smP					PS .3
	0-10	BSCL f wsbk	fri ssSP smP					PS .3
	10-36	RC MSBK	fri ssSP smP					
	36-60	RCL XWBK/ABK	fri ssSP smP 4 rock					
	0-6	BSCL GR	fri ssSP smP					PS .3
	6-50	RL SM	fri ssSP smP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ole Space (.1945)		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

ENTS: _____

DRIVE
350
2.95 AC.
59+00
58+00
57+00
56+00
20' DRAIN. ESM'T
PC = 55+54.01
14+00
Linden Falls Ct.
45' Public R/W
118'
131'
790
DRIVE
SETBACK
60'
49.65'
20' DRAIN. ESM'T
362
0.73 AC.
60x
785'
363
0.88 AC.
70x Pd
Partial Basement
125'
207'
364
0.73 AC.
70x80
120'
240'
244'
25'
30'
12" RCP
INV=773.08
127'
136'