# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

APPLICATION DATE _____

SS: _____ DATE EVALUATED: _____

SED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 345 Farm sink PROPERTY SIZE: _____

ION OF SITE: _____ PROPERTY RECORDED: _____

SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

F WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LAND-SCAPE POSITION/ SLOPE % | HORI-ZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| Front drain Slight concave | 0-20 | BSiL | WSmA fri SSSP | | | | | PS .25 |
| | 20-30 | BRC | WSmA fri SP | | | | | |
| | 30-49 | RC | ABk/SaBk fri SSP | | | | | |
| | 0-34 | RC | ABk/SaBk fri SSP | 4 motels | | | | S .25 |
| | 34-57 | RCL | MFSaBk fri SSSP | 4 motels - rock frags | | | | |
| | 0-10 | RC | MFSaBk fri SP | | | | | PS .3 |
| | 10-14 | VRCL | WSmA fri SSSP | common SAP | | | | |
| | 14-49 | R4 SCL | SAP clay mix fri SSSP | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| .ble Space (.1945) | | |
| n Types) | | |
| | | |

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

MENTS: _____

346
1.58 AC.
70x80
345
1.29 AC.
344
DRIVE
DRIVE
DRIVE
SETBACK
SETBACK
20' DRAIN. ESMT.
18"RCP
INV=774.95
INV=776.76
8"PVC
INV=783.44
8"PVC
INV=782.65
MBO
305'
290'
180'
265'
298'
307'
262'
785
790
780
78
70
72
74
76
29
28
30
92
98
96
94
90
88
86
84
82
80