SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Lee Eustler APPLICANT: Same
ADDRESS: APPLICATION DATE: DATE EVALUATED: 10/26/00
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: Lot 5 BB Creek PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-26	RC SAP	FI SSSP	Many Enc of SAP				PS .35
	26-40	RCL WSAK	FRC SSSP					
	40-56	L WSAK	FRI S=P					
	0-24	RL SBK	FI SP					PS .35
	24-44	RCL WSAK	FRI SSSP					
	44-54	L SAP	FRI NSNP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: CBP
OTHER(S) PRESENT: