SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: Ltr Foster APPLICANT: Same
DRESS: APPLICATION DATE: DATE EVALUATED: 10/24/00
)POSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
CATION OF SITE: Lot 4 BB Creek PROPERTY RECORDED:
TER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other
ALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
PE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-24	RC SNH	FRS SSSP					PS .3
	24-55	CL WSHK	FM SSSP					
	0-6	BRCL SR	FRK SSSP					PS .3
	6-16	RC SNH	FR SSP					
	16-60	RCL WSHK	FM SSSP					
~15'-20'+ to Gulley	0-12"	RC MSBK FI SS-SS, SP SE						PS .3
	12"-36"	RCL MSBK SS SP SE FR						
	36"-48"	RD/BRWCL MSBK SS SP SE FR						
		Lots Common Mica Flakes						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)		
em Type(s)		
LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: CBF
OTHER(S) PRESENT: