DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 2
PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI — APPLICANT:
ADDRESS: — APPLICATION DATE: — DATE EVALUATED: 4/3/97
PROPOSED FACILITY: — PROPOSED DESIGN FLOW (.1949): — PROPERTY SIZE:
LOCATION OF SITE: Lot 9 Harbour 6 — PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 1-5%	0-6	2g brn sl/scl	fr					
		6-30	Sprb R c/cl	fr ss so sty					
		hit	@ rock ~ 30"	hole stopped					
			PS to 30"	"					
2	L 15-18%	0-12	2g brn scl	fr					PS ~ 34
		12-34	m Sprb RC	fr ss so sty					
		34-40	m Sprb RCL	fr ss so sty					
			Inferred quartz rock Sprb						
			many fine mica flakes						
3	L 15-20%	0-12	2g brn sl/scl	fr					
		12-36	m Sprb scl/cl	fr ss so sty					
		36-48	m Sprb R-g scl	fr	4/4				
			common quartz gravel						
		Thin hole ~ 10' to	clear to spring		(PS to 48")				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: William Price APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7/14/99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	AH (A)	0-12"	Brw SCL	GR FR					PS
		12-46"	Rd/Brw CL	m-w SBK SS, SP, SE, F-FR					3- .35
		41"	Coddle + Auger						
2	AH (B)	0-12"	Brw SCL	GR FR					PS
		12-36"	Rd/Brw CL	m-w SBK SS, SP, SE, F-FR w/ Few SAP Indus					1,3 to .35
		37-48"	Yel/Rd/Gry/Brw	Loamy SAP (Need to Evaluate in Pit					36"
3	AH (C)	0-12"	Brw SCL	GR FR					PS
		12-24"	Rd/Brw CL	m SBK SS, SP, SE, F-FR					1,3- .35
		24-48"	Rd/Brw CL	w SBK SS, SP, SE, F-FR w/ Few to many SAP Indus & Mica Flakes					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____