DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI — APPLICANT:
ADDRESS: — APPLICATION DATE: — DATE EVALUATED: 5-29-96
PROPOSED FACILITY: — PROPOSED DESIGN FLOW (.1949): — PROPERTY SIZE:
LOCATION OF SITE: Hartson Phase 3 — PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☒ Public / ☒ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 4-8%	0-2	gr fsa sl	-2	1:1				.3
		2-48	sbk r cl	fi-vfi ss,sp					
2	L 2-8%	0-6	sbk rcl						.3
		6-31	sbk rc	fi sp 1:1					
		31-48	wk sbk heavy cl						
3	L 6-8%	0-6	sl/sl	fr					.3
		6-42	sbk rc	fi sp 1:1					
4		0-8	gr fsa sl	fr					.3
		8-48	sbk rc	fi sp 1:1					
			few yellow mottles						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: