DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-8-96
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 1260 gpd PROPERTY SIZE: _____
LOCATION OF SITE: Harbour phase 3 lot 42 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

Space dictated as 3 bedrooms max.

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) CONSISTENCE/ MINERALOGY	1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS 1943 SOIL DEPTH	OTHER PROFILE FACTORS 1956 SAPRO CLASS	OTHER PROFILE FACTORS 1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 8-10%	0-6 6-33 33-48	gr brwn SL SBK RC SCLSAP	fi sp l.l fi sp l.l		33"+			e3
2		0-40 40-55	L/C/CL CLSAP	fi sp l.l		40"+			e3
3	L	0-6 6-20 20-40 40-60+	gr-brwn SL/SCL SR SBK RC SBK RCL CL to CLSAPR@48"+	fi sp l.l fi sp l.l					e3
4	L	0-3 3-48 y-brown mottles beginning @ 21"+ Estr @ 40"+	gr SL SBK R heavy CL	fi-v fi sp l.l	40"+				e3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____