12373

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR George Moser DATE Oct. 17, '91 PERMIT NO. 2 E-L A-164

PHONE: Business _____ Home _____

LOCATION 1100 TR 1177 (Chuckwood) TR Barber Loop 1st lot on left

S. R. No. _____

SUBDIVISION NAME Crescent Lake Norman LOT NO. 168 2 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes ( ) No ( )

Site Suitable PS Yes (✓) No ( )

Lot Area ~1 Ac.

Character & Porosity of Soil PS clay

Percolation Rate ~.4 ft


Topography ~4% - 6%

Depth to Water Table Norman 3'+

Rock or other impervious formations none obs. ex some scattered rock

168

___ Basement with Plumbing ___ Basement without Plumbing ___ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. 900 ± Linear Ft. 300 ±

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: JB Moser

IMPROVEMENTS PERMIT BY D R Johnson, RS.

COMMENTS: Follow contour. 24" trench bottom depth on drainlines. Will accept use of 1000 gal tank already on site if it can be moved and reset without any structural problems.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold