APPENDIX H

DELL COUNTY HEALTH DEPARTMENT

SITE EVALUATION

(Ground Absorption Sewage Disposal)

R: Randy P. Howe

DATE REQUESTED: 3-30-82

ESS: Sedell

PLAT NO.: Lot 110 Holiday Harbor

TY:

LOT SIZE: 20,000ft2

TION OF SITE: 6100 TR 1177 TR 1181 Block TL Lakewood Drive ONR

FACTORS		AREA 1	AREA 2	AREA 3	AREA 4
LOPE (%)	S PS U	2-4%	S PS U	S PS U	S PS U
SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S PS U	Clay	S PS U	S PS U	S PS U
SOIL STRUCTURE (12-36 in.) (Clayey soils)	S PS U	Subangular Blocky	S PS U	S PS U	S PS U
SOIL DEPTH (In.)	S PS U	48"+	S PS U	S PS U	S PS U
RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS U	None obs.	S PS U	S PS U	S PS U
SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS U	No mottles	S PS U	S PS U	S PS U
SOIL PERMEABILITY (Percolation Rate)	S PS U	80 min	S PS U	S PS U	S PS U
OTHER (Specify)	S PS U		S PS U	S PS U	S PS U
SITE CLASSIFICATION*		PS			
SOIL SERIES		Deal			

S - Suitable PS - Provisionally Suitable U - Unsuitable

ee Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

ommendations/Comments:

ribed By: Fred Clemmer

Title: S

Date: 3-30-82

Form 2601 (2/77)

ification