SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Lee (Easter) APPLICANT: Same
ADDRESS: APPLICATION DATE: DATE EVALUATED: 10/26/00
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: lot 12 BB Creek ph 2 PROPERTY RECORDED:
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-22	RL SiL	FR SP					
	22-56	RCL mtSiL	FR SSSP					PS .3
	56-67	L SAP/wdbl	Rock FR SSSP					
	0-24	RL SiL	FR SP					
	24-48	RCL mtSiL	FR SSSP	Many SAP	Many fine to coarse			PS .3
	48-65	YRCL wSiL	FR SSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Suitable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: CBF
OTHER(S) PRESENT: