SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

NER: Lee (Easter) APPLICANT: Same
DRESS: APPLICATION DATE: DATE EVALUATED: 10/26/00
OPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
CATION OF SITE: Lot 12 BB Creek ph 2 PROPERTY RECORDED:
TER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other
ALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
PE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-22	RC SiL	FR SP					
	22-56	R/L mtSiL	cmi SSSt					R
	56-64	L SAP/w.thd Rock	FR SO					3
	0-24	RC SiL	FR SP					
	24-48	RCL mSiL	FR SSP					R
	48-65	YRCL wSiL	FR SSP	Many SAP →	Many Zone of Quartz			3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)		
em Type(s)		
LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: CBF
OTHER(S) PRESENT: