DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: C&T / Pres Robert OWNER: ____ AGENT: ____ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 7/2/85
PROPOSED FACILITY: 4BR 2 sl SFR
PROPERTY SIZE: 1.06 ac
LOCATION OF SITE: Lot 105 - Arundle
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-2	wk sbk sl	fr					.5-.8
		2-20	sbk c	fr					
		20-48	wk sbk cl	vfr					
2		0-5	wk sbk cl						
		5-15	sbk c						
		15-48	wk sbk cl						
3									
4									
5									

AVAILABLE SPACE (.1945): 5 SITE CLASSIFICATION (.1948): 5 SITE LONG-TERM ACCEPTANCE RATE: .35
EVALUATED BY: NCA OTHER(S) PRESENT: ____
COMMENTS: NR 120' Creek w/ Deep Ravine