DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 6-2-16
PROPOSED FACILITY: SFD PROPOSED DESIGN FLOW (.1949): 4BR SFD PROPERTY SIZE: ___
LOCATION OF SITE: Lot 13 Hudson Place 3 PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-14	SaLb hard fr L/cL fr						(.3) -154
		14-29	SaLb R-x cL	friss sp sp					
		29-42+	saLbg wet	Disp	42"				
2	L Slopes to back	0-3	gr- sL						-152
		3-24	SaLb f-x CL						
		24-32+	SaLb y-brn	Vfr- vs, vp (EXP)	28-36+				
					NSHG Subsurface Drainage				
3		0-10	SaLb brn fr/sh	fr 1:1					<3
		10-22	SaLb wet	fr sp 1:1					
		22-46+	SaLb n cL	fi sp/pl					
			ndio mottles 40+						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___