DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 4-24
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Lot 8 Hanlon phase 3 — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well / ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 6-8%	0-14	Sa b c	fr-fi sp					3
		14-33	f SL SaLo / cl Sa	fr ss-p	35"+				
		33-37+	Sa Lo R-y	hard cl Sap					
2	L 4-6%	0-12	gr bank SL Ksk	fr					≤15 LTAR
		12-32	SaLo EC	fi so fi/mod					
		32-48	(w)k Sa Lo y-brn cl	fr so fi/mod 40"					
			(w) fault - clay 2 mottles 40"+						
3	L 4-6%	0-19	gr f SL	fr					≤15 LTAR
		19-38	gr-	fr ss-p	36"+				
4	L eroded 6-8%	0-7	SaLo heavy C2B	fr so					
		7-14	cl/sicl sapric	fr ss-p					
		14-34	(brn) SiCl Sa (basic)	fr-fi ns-p					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

EXISTING pits excluded mostly 24" max wall - silt/clay fr LPP proposed
1 Apt Shear strp/ct sing = 24"