IREDELL COUNTY HEALTH DEPARTMENT

(TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Henry D. Byrd DATE 7-24-80 PERMIT NO. 224

TYPE: Business _____ Home _____

LOCATION 1100 TR 1177 TR just before 1458 at end TR lot on left - Aluminum siding building (A FRAME) S. R. No. _____

SUBDIVISION NAME Holiday Harbor LOT NO. 30 SECTION OR BLOCK NO. _____

House (X) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Sewage Disposal Unit Yes ( ) No (X)

Auto. Dishwasher Yes (X) No ( )

Auto. Wash. Machine Yes (X) No ( )

Site Suitable Yes (X) No ( )

Character & Porosity of Soil Clay loam

Percolation Rate 30 min per in


Topography 15-25%

Depth to Water Table 4'

Rock or other impervious formations NONE OBSERVED

Lot Area ~½ Acre

_____ Basement with Plumbing _____ Basement without Plumbing X No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 5

Sq. Ft. 750 Linear Ft 250

Depth of Stone in Lines 16"

Water Supply: Individual (X)

Public ( )

Installed by Blake Hyde

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY David R. Henson

COMMENTS: System deep (about 7' on upper side of bed 4½' on lower side - Depth due to presence of fill dirt

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 7-24-80

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold