DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: The Farms LLC APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 2-8-05
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 400gpd PROPERTY SIZE: ___
LOCATION OF SITE: lot 391 The Farms PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-7	wkSbk brn vfr	frssso					o3
		7-20	mfSbk RdBr	frssp sso					
		20-51	wkSbk RdBr/C	frssp	few mi SAP				
2	11% S	0-4	mgr. sdl	frsssp					o3
		4-24	mssbk RdBr	frsssp SAP					
		24-52	wkSbk L	frsssp	few mi SAP				
3		0-10	wkSbk brn sdl	frsssp					o3
		10-33	mfSbk RC	frsssp SAP					
		33-48	wkSbk RdBr	frsssp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	pump 25% Red	pump LPP 25-50% Red
Site LTAR	o3	o3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [signature] Paul Pennington & Kathleen TCT
OTHER(S) PRESENT: ___

COMMENTS: ___


160'
135'
pm
Col Pepsi
391
1.31 AC.
390
1.42 AC.
75'
70 x 100
DRIVE
DRIVE
403'
Kemp Dr
246'
221'
800
795
790
357
10' DRN ESM
135'
160'