DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Daniel Warren
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 9-18-08
LOCATION OF SITE: 471 Agnew Rd PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5-10%	0-16"	CMABK	SSSPSexpF	R	[redacted] 56"	inc	—	.35
		16-56"	CLMSBK	SSSPSexpVF					
2	5-10%	0-28"	CMSBK	SSSPSexp	small area A chroma 3 around 24" less than 2% of pit Possibly lateral water movement (Isolated)	65"	—	few rock	.3/.35
		28-65"	CLWSBK	SSSPSexp					
3	5-10%	0-14"	CMABK	SSSPSexp	—	36"	inc 36"	—	.35
		14-36"	CLMSBK	SSSPSexpVF					
		36-56"	LSAPWSBK	SSSPSexpVF					
4	5-10%	0-15"	CMABK	SSSPSexpF	—	47"	inc 20"	—	.35
		15-47"	CLMSBK	SSSPSexpVF					
		47-60"	LSAPWSBK	SSSPSexpVF					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity Panel	LP-Panel
Site LTAR	.35	.35

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____