TMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
N OF ENVIRONMENTAL HEALTH
E WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Lee Easter
ADDRESS: _____
PROPOSED FACILITY: _____
LOCATION OF SITE: Lot 6 Thurston Dr
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

APPLICANT: _____
APPLICATION DATE: _____
PROPOSED DESIGN FLOW (.1949): 360
DATE EVALUATED: 1-17-96
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

now Lot 5

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | LSS 4-6% | 0-8 | sab - RCL | 1:1 fr | | | | | .57 |
| | | 8-17 | sab RC | 1:1 fr sp | | | | | |
| | | 17-40 | sab RCL | 1:1 fr | | | | | |
| | | 40-47 | tuk sab p | 1:1 fr | | | | | |
| | | | | | | | | | |
| 2 | LSS slight 8 conc 10% | 0-10 | | | | | | | .57 |
| | | 10-33 | tan RC | fr sp | | | | | |
| | | 33+ | tuk sab RCL | fr | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____