DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: John McVannon
ADDRESS: ___ APPLICATION DATE ___
PROPOSED FACILITY: ___ DATE EVALUATED: 5-10-05
LOCATION OF SITE: 228 Chuckwood PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: ___
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	New System Area 5% Linear	0-5	lsbk cl			48			.3
		5-36	vfsbk c	fr ss/sp/se					
		36-48	lsbk c +						
			few incl.						
			Sap						
2	Near Existing & New Addition	0-10	lsbk cl			48			.25
		10-36	lsbk/absk c	fi ss/sp/se					
		36-48	lsbk/absk cl	fi					
3	Repair	0-4	lsbk cl			48			.3
		4-40	lsbk c	fr ss/sp se					
		40-48	lsbk cl						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	Yes	Same
System Type(s)	25% rm	
Site LTAR	.3	

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): P5
EVALUATED BY: J. Melville
OTHER(S) PRESENT: ___

COMMENTS: ___