VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: Melissa Miller APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5/29/2001
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Holiday Harbour Lot 116 PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
AH-1 Initial	0-4"	Brw SCL	GR FR					PS .3
	4"-18"	R C mSBK	SS, SP, SE, FI-FR					
	18"-48"	Rd/Brw C/C m-w SBK	SS, SP, SE, FR					
AH-2 Repair	0-10"	Brw SCL	FR GR					PS .3
	10"-48"	Rd/Brw C/C m-w SBK	SS, SP, SE, FI-FR w/very Few yel/brw mottles					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
OTHER(S) PRESENT: _____