4626-66-8848

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR RSMB Enterprises DATE Sept. 30, '87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 TR 1115 (McKendree) TR (3rd) 2nd entrance into Brookridge near end on Right S. R. No. _____

SUBDIVISION NAME Brookridge Shores LOT NO. 87 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2


Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Clay
Percolation Rate ~1.4 gpd/ft²
Topography 4-8% near road (15%+ near lake)
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area ~20000 ft²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement

1000 gal pump tank



Plot of System N.T.S.

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. _____ Linear Ft. 60' of Trench
Depth of Stone in Lines 16"
Water Supply: Individual ( ) panels
Public ( ) pressure closet

Installed by Levon Benton

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Andrew C. Pierce

IMPROVEMENTS PERMIT BY DRH

COMMENTS: panels and tanks ckd by DRH. ck checked pump for pressure head (18") and alarm for high water mark.

CERTIFICATE OF COMPLETION BY Andrew C. Pierce DATE 9/30/87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold