PARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: CRI APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 5-2-03
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: ___
LOCATION OF SITE: Lot 58 Lakeforest PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-15	mfriablekyprc	frss fewgbrnmottles					.3
		15-48	mfsbkyprc	frss					
		48-60	kysl stp	frsssp					
2	6%	0-8	gr brnsl	frsssp					.3
		8-24	mfsbk brnc	frss stp					
		24-41 (36")	mfsbk/fri yrc	frsssp few cmmn mfstp					
		41-54	LSstp	frsssp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	1pn 25% red	1pn 25% red
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [signature] Paul Pennington
OTHER(S) PRESENT: ___

COMMENTS: ___


COTT HILL
PG 360
430'
135'
135'
825
820
815
810
805
Contour
15' SIDE YARD SETBACK
334'
386'
167'
125'
293'
58
1.03 Ac.
57
1.25 Ac.
56
0.83 Ac.
ASPEN CREEK DRIVE
45' PUBLIC R/W
35' FRONT YA
125'
125'
125'
145'
74'