DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CBS APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 480 gpd DATE EVALUATED: 4/17/03
LOCATION OF SITE: 48A SFE LAKE FRONT PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

Now SFE 47A

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	7-8%	0-4	wksbk RbrnL	frssp					
		4-17	mfsbk RC	frsssp Sapp					.25-.3
		17-48	wkfsbk yRCL	frsssp	mod ywr on end of pit				
2	~7%	0-28	mfsbk R-grCL	frsssp	textural chg				
		28-SD	(C-B) wkfsbk LCL	frssp					.3
3		0-34	w.mfsbk RCL	frsssp sapp					
		34-SD	wkfsbk grL	frssp					.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS per 1952
System Type(s)	PM 25% Red.	LPP PBPS
Site LTAR	.25-.3	.25-.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): P
EVALUATED BY: DLK Paul Zimmerman
OTHER(S) PRESENT: _____

COMMENTS: _____