DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CRE  APPLICANT: _____
ADDRESS: _____  APPLICATION DATE: _____  DATE EVALUATED: 3.12.99
PROPOSED FACILITY: _____  PROPOSED DESIGN FLOW (.1949): _____  PROPERTY SIZE: _____
LOCATION OF SITE: Lot 366 Phase II Thrift  PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

996-6330
Paula NEW main

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | #1166 TC | 0-11 | gg cl loam w/ f-m | | | | | | PS .3 |
| | | 11-36 | sab w/ brn & gy mott | fr | few silt | | | | |
| | | 36-48 | wk fsab | dull gye | many | fr | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | 0-28 | fill | | | | | | PS 1.25-.3 |
| | | 28-40 | mfsab RC | fr SSP | | | | | |
| | | 40-59 | wksab RY | fr SSP common in SSP | | | | | |
| | | | on other wall slope @ 58" | | | 46"b | | | |
| | | | | | | | | | |
| | | 0-20" | fill | | | | | | PS 1.25 |
| | | 20-33½ | compacted fill | | | | | | |
| | | 33½-42 | sab | rd | fr SSP | | | | |
| | | 42-65 | LSAP | fr SSP | | 46"b | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ailable Space (.1945) | | |
| tem Type(s) | | |
| LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____