DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-12-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 273 phase 3 Taft PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-23	mfrabpc	fr SP					PS .3
		23-60	msbk yrck few common	fr ss sp					
2		0-6	sg brwsl	fr					PS .3
		6-33	mfrabpc	few/common fr ss sp					
		33-54	msbk yrck common	fr ss sp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)		
ystem Type(s)		
te LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

BRAWLEY SCHOOL ROAD, S.R.
35'X90' LANDSCAPE & SIGNAGE EASEMENT (TYP)
C1
N 21°37'49" W 140.18'
35' MBS
S 68°26'11" W 97.25'
N 68°26'11" E 186.56'
R/W
EP
35' MBS
272
43,529 SF
0.999 AC
70 x 80
15" RCP
C2
DRIVE
N 81°26'59" W 69.64'
N 02°30'52" W 244.23'
N 9°10'14" W 73.89'
48.27'
25.72'
CRAWL
BASEMENT
80
273
41,376 SF
0.950 AC
C3
N 74°19'43" W 90.30'
N 15°10'56" E 276.88'
29.98'
15" RCP
N 70°15'41" W 125.46'
274
35,256
0.809
CRAWL
BASEMENT
80