SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: CRT APPLICANT:
DDRESS: APPLICATION DATE: DATE EVALUATED: 4-8-99
OPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
OCATION OF SITE: Lot 35 PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-10	gr brn sdy fr						PS .3
	10-53	Sprb RC	fr SS-S					
	53-58	Sprb VFSL	mlsy fr	10YR 6/2				
	0-20	[illegible] RS	[illegible]	somewhat compacted				PS .3
	20-53	[illegible] VFSL	fr SS-S					
	53-58	[illegible] VFSL	fr Sprb					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)		
ystem Type(s)		
te LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

...-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

...ER: PRT APPLICANT: _____

...DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4-9-99

OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: Lt NE of Lot 357 (SFE) @ 377 cos PROPERTY RECORDED: _____

...TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

...ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

...PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

...1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-15	Sab p c/cl	dkyb-brn mott fr sp-ss p					
	15-60	vk gr/ms RCL	fi ss sp	?				4
			[illegible]	20"+				
...ly in 377 cos	0-12	gr s/sandy fsc	ss sp					3
	12-52	m-cm RC	fi sp	[illegible]				
...ond 258	0-3	[illegible] sdcl/ scl						3
	3-54	m-cm RC	vfr sp					
		[illegible]						
...behind 259/255	0-26	m-cm RC						P
	26-60	[illegible]	[illegible]	[illegible]				

...DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...able Space (.1945)		
...n Type(s)		
...TAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____