DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

gm

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Deb House — APPLICATION DATE _____
ADDRESS: _____ — DATE EVALUATED: 12/2/2010
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Poplar Grove #49 — PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut — TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4%	0-3"	Brw SCL						PS
		3-36"	Rd C/CL	m-wSBK	SS,SP,SE,FR				
		36-48	Rd/Yel	C w/SBK	SS,SP,SE,	FR w/few to			.3
			many	SAP Indus	—	48"	—	—	
2	L 4%	0-3	Brw SCL						PS
		3-34	Rd C m SBK	m SBK	SS,SP,SE,FR				
		34-48"	Rd to Yel/Rd C/CL	m-w	SS,SP,SE,FR				wf .3
			few Yel/Brw	Indus	—	48"	—	—	
3	L 24%	0-6	Brw	SCL	SS,SP,SE,FR				PS
		6-34	Rd C/CL	m-wSBK	SS,SP,SE,FR				
		34-48	R C/L	w/SBK	SS,SP,SE,FR				
			w/few to many		SAP	Indus > 40"	—	—	.3
					—	48"			
4	L 3-4%	0-3	Brw	SCL	SS,SP,SE,FR				PS
		3-48"	R to RCL	CL SS	SP,SE,FR				
			w/	some SAP	Indus				.3
					—	48"	—	—	

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	LP Panel Blk	Same
System Type(s)	IV	IV
Site LTAR	.3	.3

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: _____

COMMENTS: _____