IREDELL COUNTY HEALTH DEPARTMENT 4626-94-4127

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Hartley Corp. DATE 9-13-94 PERMIT NO. _____

PHONE - Business 664-3515 Home _____

LOCATION 1100 [redacted] at Intersection of 115

S. R. No. _____

SUBDIVISION NAME Brawley Farms LOT NO. 3 SECTION OR BLOCK NO. _____

House ✓ Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2 Character & Porosity of Soil Clay loam / Porosity Fair


Garbage Disposal Unit Yes (✓) No ( ) Percolation Rate Soil borings

Auto. Dishwasher Yes (✓) No ( ) Topography 20% slope

Auto. Wash Machine Yes (✓) No ( ) Depth to Water Table 10'+

Suds Soluble Yes (✓) No ( ) Rock or other Impervious formations none

Property 20,000 Sq. Ft.



Size of Tank 1250 Gals

Nitrification Field:

No. of Lines 3

Sq. Ft. 625 Linear Ft. 252

Depth of Stone in Lines 10"

Water Supply: Individual ✓

Public ( )

Installed by F. J. Ervin

IMPROVEMENTS PERMIT BY John Houston

COMMENTS _____

CERTIFICATE OF COMPLETION BY [signature] DATE 9-13-94

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold