DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

# SOIL/SITE EVALUATION *for* ON-SITE WASTEWATER SYSTEM

OWNER: Lillian Johnson
ADDRESS: ___ APPLICATION DATE 8/22/02 (waiting for survey)
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 600 GPD. DATE EVALUATED: 10/4/02
LOCATION OF SITE: Poplar Grove + Blanc. Lake Rd. PROPERTY SIZE: ~12.25 Ac
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 13-14 Ridge Side (W) | 0-27 | SBK / SC | FR SS SP | R CH2 | | | | .25 .3 |
| | | 28-35 | <CH2 1HCL SBK SC | FR SS SP | | | | | |
| | | 36- | | FI S - SP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | 13-14 Ridge Side (W) | | | | CH2 (W) | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | 22-24 | 4R MAT SBK R / SC | FR SS - SP | | | | | |
| | | 25-37 | 4R CH2 1HCL SCl | FR SS SP | | | | | |
| | | 38 | | | | | | | |
| 3 | 13-14 Ridge Side (W) | 0-4 | SBK / SC | FI SS SP | | | | | .25 .3 |
| | | 5-27 | SBK / SC | FR SS NP | | | | | |
| | | 28-31 | SBK cncl | 1PRINCE FI S - SP | | | | | |
| | | 32-49 | SBK SLIGHT | 1PRINCE FR S SP | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): very well drained (deep) - irregular
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___