DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Jim Hodgkinson OWNER: ___ AGENT: ___ PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 2-1-95
PROPOSED FACILITY: ____
PROPERTY SIZE: ____
LOCATION OF SITE: Lot 12 Ponta Grande
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	R-55	0-5	wk sbk sc	vfi fri (wet) m. plas/sti			05		-3
		5-18	sbk c	vfi mfi					
		18-48	wk sbk cl	vfi fi-fr					
			some silty mottles						
2	L55	0-8	gr-wk sbk sc	Stky					-3
		8-18	sbk c	mfi					
		18-48	wk sbk cl	fi-fr/fe					
3									
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____
EVALUATED BY: DPH OTHER(S) PRESENT: ____
COMMENTS: 2-1-95 Site needs "cleaning up of brush" to evaluate in order to determine septic system layout