4627006548

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Theresa Featherwood DATE 4-19-74 PERMIT NO. 93

PHONE: Business _____ Home 827-4539

LOCATION 1100 TR on 1115 TR on 1455 TL then TR 2nd Rd TL at end S. R. No. 1455


SUBDIVISION NAME Lake Norman LOT NO. 284 SECTION OR BLOCK NO. 8

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay loam Porosity Fair
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	53 min/inch
Auto. Wash. Machine	Yes ( )	No (✓)	Topography	20° Slope
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	8 to 10' above Lake Level
			Rock or other impervious formations	None

Lot Area 3/4 acre



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"

Water Supply: Individual (✓)
Public ( )

Installed by John Howie

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: small area to put tank in therefore pushed property line and entos line is within 50'. However it is well above Lake Level.

CERTIFICATE OF COMPLETION BY J. C. Moore DATE 4-19-74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

4627006548

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

78

OWNER OR CONTRACTOR Theresa Featherwood DATE 3-25-74 PERMIT NO.

PHONE: Business Home 827-4539

LOCATION 1100 TR on 1115 5th Rt TR on 1455 2mi TR out on end of Point S. R. No. 1455

SUBDIVISION NAME Lake Norman LOT NO. 284 SECTION OR BLOCK NO. 8

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes ( )	No (✓)	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil clay loam Porosity Fair


Percolation Rate 53 min/inch

Topography 20% slope

Depth to Water Table 10+

Rock or other impervious formations none

Lot Area 3/4 acre



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 625 Linear Ft. 250

Depth of Stone in Lines 10"

Water Supply: Individual (✓)

Public ( )

Installed by

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: Percolation Test is within acceptable range.

CERTIFICATE OF COMPLETION BY DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold