DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___
4627 21 05 TA

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: James Crosman APPLICANT: ___
ADDRESS: 314 Lake View Shore Dr. APPLICATION DATE: ___ DATE EVALUATED: 7/23/08
PROPOSED FACILITY: Home PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: .71 AC
LOCATION OF SITE: Semora CL+T Sec 8 - 310 PROPERTY RECORDED: < 1983
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 11-12% (L)	0-8	SM sbk / c	VFI SS-SP	P				
		9-30	MF sbk / cl	MIC SEXP FR SS-SP					
		31-49	MM sbk / cl	MIC SEXP VFR - SS SP					
2	(R) 13-15%	0-11	SM sbk / c	MIC VFI SS - SP	D				
		12-34	MM sbk / cl	MIC SEXP FR - SS - SP	m - R				
		35-49	MM sbk / scl	MIC VFR - SS - SP	m - YR				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	< 1983
System Type(s)	Trench PPBRS	
Site LTAR	.3	

OTHER FACTORS (.1946): Road Rev Well location
SITE CLASSIFICATION (.1948): PS - No Repair
EVALUATED BY: Sperko
OTHER(S) PRESENT: B. Fisher