VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: John & Terry Fink APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 4/2/2001
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Gant Hill Rd PROPERTY RECORDED: _____
ATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
IN Back	0-26	Rd/Brn C/C	mSBK S, SP, SE, FR					PS .3+
	26-48	Rd/Brn C	wSBK SS, SP, SE, FR w/ Common Mica flakes					
IN Front	0-4	Brn SiC	GR FR					PS .3+
	4-24	R C/C	mSBK SS, SP					
	24-48	Rd/Brn C	C wSBK SS, SP, SE, FR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____