4627500589

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Frank Mangum DATE 12-2-83 PERMIT NO. 412

PHONE: Business _____ Home _____

LOCATION 1100 TR 1115 TR 1457 Bear Rt 2nd Road to R Near End, on R

S. R. No. _____

SUBDIVISION NAME Lake Norman LOT NO. 397 SECTION OR BLOCK NO. 8

House (X) Mobile Home ( ) Business ( ) Other Adding Garage – utility building

House 3 2

No. Bedrooms 0 No. Bathrooms 0

Character & Porosity of Soil Top Soil – Weathered grn to 18"

Garbage Disposal Unit Yes ( ) No ( ) Percolation Rate 120F


Auto. Dishwasher Yes ( ) No ( ) Topography 25%

Auto. Wash. Machine Yes (X) No ( ) Depth to Water Table 24"

Site Suitable Yes ( ) No ( ) Rock or other impervious formations 21 / Clay at 24"

Lot Area Existing & Road

X Basement with Plumbing ___ Basement without Plumbing X No Basement



Plot of System

Size of Tank 75 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 360 Linear Ft. 120
Depth of Stone in Lines 12"

Water Supply: Individual (X)
Public ( )

Installed by Richard Abernathy
I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY David Hinson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 12-2-83

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Frank Mangum DATE 9-22-82 PERMIT NO. 87

PHONE: Business _____ Home _____

LOCATION 1100 TR 1115 TR 1457 Bear Rt. 2nd rd. to Rt. near end on Rt. S. R. No. _____

SUBDIVISION NAME L.N. LOT NO. 397 SECTION OR BLOCK NO. 8

House (✓) Mobile Home ( ) Business ( ) Other Adding Garage - utility bldg


No. Bedrooms House 3 Utility 0 No. Bathrooms 2 0

Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes ( ) No ( )

Character & Porosity of Soil topsoil weathered p.m. to 18"
Percolation Rate 120 ft
Topography 25%
Depth to Water Table 24"
Rock or other impervious formations 2:1 clay at 24"

Lot Area Existing

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement for washer



Plot of System

Size of Tank 75 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 360 Linear Ft. 120
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

X Signed: Frank Mangum

IMPROVEMENTS PERMIT BY [signature]

COMMENTS: Drainfield must be installed very shallow Use 6" natural cover + 6" fill dirt.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold